



# East Sidewalk Pavement Markings

PBAC Meeting – 11/8/23


# South Access to Bridge



## South Access Signage - Similar to but Different than North Signage




# Bike/Peds in Correct Lanes



#### Three Abreast Peds and Bikes



- Stencils not Continuous May Impact Behavior.
- Bike Path Width and Bike Stencil Does not Conform to the Caltrans Highway Design Manual (HDM).
- Arrows vs Sharrows.



# Conforming Behavior




## Crowds of Peds Intrude into Bikeway #1




#### Crowds of Peds Intrude into Bikeway #2




## Crowds of Peds Intrude into Bikeway #3




Crowds of Runners Intruding into Bikeway



# Conforming Use



# Conforming Use #2



Large Crowd Intruding into Bikeway




Peds Intruding into Bikeway



# Conforming Use



#### Narrow Southern Access Point



#### Narrow Southern Access Point with Bicycles

